

### ARC/FR Sweatband for Hard Hat

#### MATERIAL

- \* Polartec® Power Dry® FR
- \* 47% Rayon / 38% Modacrylic / 15% Para-aramid
- \* 6.4oz knit
- \* Inherently flame resistant
- \* Grey colour

#### FEATURES

- \* Attaches to hard hat suspension unit with snaps
- \* Highly breathable
- \* Odour resistant
- \* Superior wicking action
- \* Soft surface provides maximum comfort
- \* Machine washable

#### COMPLIANCE

- \* Meets ASTM F1506
- \* ARC Rating: ATPV = 9.8 cal/cm<sup>2</sup>

#### CONSTRUCTION

- \* Standard AGO heavy duty construction
- \* Sewn with flame resistant thread

#### PACKAGING

- \* Individually packed in a clear polyethylene bag

#### SIZING


- \* One size fits all




## Installation Instructions

ARC/FR Sweatband for Hard Hat  
**AGO #SP-367-35**


INSTRUCTIONS FOR USE:



**Step 1:** Position the sweatband with the male snaps facing down and toward the front of the hard hat.



**Step 2:** Tuck the male snaps between the front of the suspension band and the inside front of the hard hat. Bring the female snaps around under the suspension band to meet the male snaps. Snap together.



**Step 3:** Adjust the sweatband into the proper position so that all snaps are on the outside and the fabric is smooth on the inside of the suspension band.

AGO INDUSTRIES INC. | LONDON, CANADA 2015